AIRAC

# - IRELAND -

IRELAND 1 - 2

 Phone:
 +353 (0)61 703 750

 Fax:
 +353 (0)61 366 245

 AFS:
 EINNZPZX

 Email:
 aisops@iaa.ie

 URL:
 https://www.iaa.ie

Irish Aviation Authority Aeronautical Information Service Ballycasey Cross Co. Clare V14 C446 IRELAND AIP SUP: 016/2022 Effective Date: 14-JUL-2022 Publication Date: 02-JUN-2022 End Date: Publishing Organisation: IAA

## **Dublin Airport (EIDW)**

## Refurbishment of Airfield Perimeter Road South of Runway 10R\_28L PHASE 1 and PHASE 2

For a period of about 25 weeks commencing the 2nd July 2022 works will be in progress on the initial phases of a project to refurbish the Southern Airfield Perimeter Road at Dublin Airport. This supplement concerns Phase 1 and Phase 2 of the works only.

The works described in this supplement form part of a more extensive overall project. Further supplements will be issued in due course, with details of later phases.

The working locations for each phase are shown in the appendix to this supplement. Working Areas will be marked and lighted as necessary.

Times and durations of works are indicative only. Exact dates and times of works will be promulgated by NOTAM in due course, with reference to this supplement. Times and durations may vary over the course of the project and within work phases.

In the event of Low Visibility Procedures being implemented or forecast no works will be undertaken in any phase.

### Phase 1

All works and construction equipment in this area will remain clear of all Obstacle Limitation Surfaces for Runway 10R/28L and Runway 16/34.

It is intended that works in this phase will commence on the 2nd July 2022 and will be ongoing for 25 weeks. Working hours will be 0800Hrs to 1800Hrs (Local time).

#### Phase 2

All works and construction equipment in this area will remain clear of all Obstacle Limitation Surfaces for Runway 10R/28L.

It is intended that works in this phase will commence on the 9th September 2022 and will be ongoing for 1 week. Working hours will be 0800Hrs to 1800Hrs (Local time).

During the working hours of this Phase, Runway 16/34 will be withdrawn from service for all take-offs and landings.



